



Attorney Docket No. 1504.1023

IN THE UNITED STATES PATENT AND TRADEMARK OFFICE

In re Patent Application of:

Motoaki TANI et al.

Application No.: 10/644,004

ATTENTION

Confirmation No.: 4861

CERTIFICATE OF CORRECTION

Filed: August 20, 2003

BRANCH

U.S. Patent No.: 6,869,665 *B2*

Batch No.:

Issued: March 22, 2005

For: WIRING BOARD WITH CORE LAYER CONTAINING INORGANIC FILLER

REQUEST FOR CERTIFICATE OF CORRECTION

Commissioner for Patents
PO Box 1450
Alexandria, VA 22313-1450

Certificate
AUG 19 2005
of Correction

Sir:

Patentee(s) respectfully request(s) that a Certificate of Correction be issued in the subject patent, pursuant to 35 U.S.C. §254 and 37 C.F.R. §1.322, to correct the mistake(s) shown on the attached Form PTO-1050.

Since the mistakes are Patent Office mistakes, it is believed that no fee is required.

Respectfully submitted,

STAAS & HALSEY LLP

Date: 8/17/05

By: Richard A. Gollhofer
Richard A. Gollhofer
Registration No. 31,106

1201 New York Ave, N.W., Suite 700
Washington, D.C. 20005
Telephone: (202) 434-1500
Facsimile: (202) 434-1501

AUG 22 2005

Under the Paperwork Reduction Act of 1995, no persons are required to respond to a collection of information unless it displays a valid OMB control number.
(Also Form PTO-1050)

UNITED STATES PATENT AND TRADEMARK OFFICE

CERTIFICATE OF CORRECTION

PATENT NO : 6,869,665 *B2*

DATED : March 22, 2005

INVENTOR(S) : Motoaki TANI et al.

It is certified that error appears in the above-identified patent and that said Letters Patent are hereby corrected as shown below:

Column 12, line 63, change "aver" to --layer--.

Column 13, line 17, delete "." after first "°C";
line 22, delete "." after first "°C".

Column 14, line 5, delete "." after first "°C";
line 10, after "% of " insert --the--.

MAILING ADDRESS OF SENDER:
STAAS & HALSEY
1201 New York Avenue, N.W.
Suite 700
Washington, DC 20005

PATENT NO. 6,869,665

No. of add'l copies
@ 304 per page

⇒

AUG 22 2005